



**ZENNER PMCB Bronze Compound Meters
(No Strainer Attached)
Typical Head Loss Curves**



**ZENNER PMCB Bronze Compound Meters
(No Strainer Attached)
Typical Head Loss Curves**

