





ZENNER ZTM and ZTMB Turbine Water Meters (Without Strainer) Typical Head Loss Curves



ZENNER ZTM and ZTMB Turbine Water Meters (Without Strainer) Typical Head Loss Curves

